

Risk assessment

Download Link: [#306 - Embroidery Machine - 260702.pdf](#)

#	Identify Hazards	Risks	Who maybe Harmed	Severity	Control Measures	Likelihood	Risk Rating
1	Electricity	Electric shock	User	High	All power tools should be checked for electrical safety prior to use. They should have a PAT test label on. It is the users responsibility to do a visual check of the tool. If any defects are found i.e. cracked casing, defect in lead etc. If defect found the tool is not to be used, be quarantined and a defect label attached.	Low	Med

2	Misuse of equipment	Damage to user or equipment	User, Bystander	High	Members are inducted into the correct use of the equipment and understand associated risks. Members found to be deliberately misusing equipment may have their use of the machine restricted or revoked altogether.	Low	Med
3	Sewing Needle (In Use)	Piercing Injury	User	High	Required induction covers safe usage, First aid kit available in kitchen	Med	Med
4	Sewing Needle	Cutting Self on Needles	User	Low	First aid kit available in kitchen	Low	Low
5	Ejection of Broken needle from machine	Piercing Injury, Laceration Injury	User	Med	Induction covers the risk of sewing over decorations and the importance of needle changes. Induction covers changing needles. First aid kit provided in kitchen	Low	Med

6	Fast moving Parts	Trapping Injury	User	Med	Machine will fail movements before major injury Induction process covers not touching the equipment during operation	Low	Low
---	-------------------	-----------------	------	-----	--	-----	-----

Revision #3
Created 2026-07-01 00:58:26 UTC by Admin
Updated 2026-08-19 19:17:27 UTC by Jacob Lucas